## F/A-18 Wiring System Awareness

## PREVENTING WIRING SYSTEM FAILURE

SAVES TIME, MONEY...





Deteriorated clamp causing chafing.



Harness chafing on fuel line.

## **ALWAYS MAINTAIN THE CORRECT WIRING SYSTEM CONFIGURATION!**

